



Product Description: Toro Power Sweep Electric Blower

The recall involves Toro Power Sweep electric blower model 51586 that was manufactured between 2000 and 2002. The electric blowers have serial numbers that range between 000055100 and 220255609. There are two decals on the main housing of the blower. One decal reads, "TORO Power Sweep" and the decal on the opposite side of the blower contains the model number and serial number. The recalled units can be identified by a black impeller fan, which can be seen through the air inlet screen on the bottom of the unit.

Manufacturer: The Toro Company, of Bloomington, Minn.

Date Recall Posted: 7/26/07

UPCs: N/A - Meijer has not carried this product for several years.

Summary Of Recall: The blower's impeller, which is a rotating component on the blower, can break, resulting in pieces of plastic flying out of the blower. This poses a risk of serious injury to the user or a bystander.

What You Should Do: Consumers should stop using the recalled blowers immediately and contact Toro to receive a replacement blower.

For more information, contact Toro at (888) 279-3191 between 7:30 a.m. and 7 p.m. CT Monday through Friday or 8 a.m. and 6 p.m. Saturday. Consumers can also visit the Toro web site at www.toro.com. The Toro Company has notified registered owners directly.