



Product Description: Sevylor® Tow Behinds with Quick Hitch Connectors. The recall involves the following model Sevylor® Tow Behinds with Quick Hitch component. The Quick Hitches were manufactured between 2005 and 2009.

Manufacturer: Shanghai Suofeng Plastic Metal Manufactures Co., Ltd., China

Importer: Sevca, LLC of Wichita, KS

Date Recall Posted: 7/23/09

UPCs:

UPC	Description	Key
00000000-89736-35006-1	SEVYLOR LEBISCUIT TOW BEHIND	49
00000000-89736-35044-3	SEVYLOR BLITZ TOW BEHIND 54"	49
00000000-89736-35069-6	SEVYLOR DRAGON MASTER TOW BEHIND	49
00000000-89736-35077-1	SEVYLOR EASY DRIFTER TUBE FOAT 54"	49
00000000-89736-35080-1	SEVYLOR DAYTONA 1 PERSON TOW BEHIND	49
00000000-89736-35232-4	SEVYLOR FEARLESS TUBER ST2000-8	49
00000000-89736-35252-2	SEVYLOR BLITZ TUBE 54" ST2500CP-6	49

Summary Of Recall: The Quick Hitch, which connects the towable to the boat, can break and project pieces of the plastic Quick Hitch back towards the boat. If this occurs, an individual can be struck and seriously injured.

What You Should Do: Consumers should immediately stop using their recalled tow behinds and contact Sevca to receive instructions on how to remove the Quick Hitch from their tow behind and use the tow behind without the Quick Hitch. Consumers will receive a 1-2 person tow rope for returning the Quick Hitch.



**Consumer Contact
Information:**

For more information, contact Sevca at (800) 356-3612 between 7:00 a.m. and 4:45 p.m. CT Monday through Friday or visit the firms' Web site at www.sevylor.com