



Product Description: Dorel Juvenile Group is conducting a voluntary recall of certain Safety 1st, Cosco, Disney and Eddie Bauer Designer 22 Infant Child Restraints and therefore we are requesting the stop sale of these products.
The Infant Child Restraints were sold with Travel Systems.

Manufacturer: Dorel Juvenile Group

Date Recall Posted: 12/14/2009

UPCs:

Travel System Model Number	Child Restraint Model Number
01-004DBY	22-057 DBY
01-004IDBY	22-057 DBY
01-012DWA	22-085 DWA
01-051CLN	22-057 CLN
01-051HRT	22-057 HRT
01-079CGT	22-627 CGT
01-079FRK	22-627 FRK
01-079SNW	22-627 SNW
01-079WPR	22-627 WPR
01-132HRR	22-322 HRR
01-132PTK	22-322 PTK
01-170LPH	22-057 LPH
01-170LPHA	22-057 LPH
01-172LYN	22-085 LYN
01-432WAV	22-627 WAV
01-442KDL	22-322 KDL
01-442LXI	22-322 LXI
01-442OLY	22-322OLY
01-442PRS	22-322PRS
01-552MAI	22-322 MAI
01-573LGA	22-380 LGA
01-573MSA	22-380 MSA
01-749KGS	22-627KGS
01-773BYTE	22-655 BYTE
01-905COB	22-325 COB
01-929IPAC	22-325 PAC
01-929PAC	22-325 PAC
01-938CSF	22-300 CSF
01-938FZN	22-300 FZN
01-938JJV	22-300 JJV
01-938OSF	22-300 OSF
01-938THD	22-300 THD
01-938THDW	22-300 THD
01-938TWD	22-300 TWD



01-959AWF	22-627 AWF
01-968LBF	22-355 LBF
01-987INAB	22-305 NAB
01-987NAB	22-305 NAB
01-987PPH	22-305 PPH
01-996RBK	22-095 RBK
TR043PWK	22-355 PWK

Summary Of Recall:

The child restraint handle bolt can loosen causing the handle to fully or partially separate from the seat. This may cause the child to fall out of the seat if they are in the seat unharnessed. The bolt loosening does not affect the safety of the infant child restraint for use in a vehicle. The Designer 22 Infant Child Restraint Systems were sold with Travel Systems. The stroller portion of the travel system is not affected by this recall.

What You Should Do:

Consumers should call -(866)762-3316

**Consumer Contact:
Information:**

Consumers should call -(866)762-3316.