



Hinge Affected



Hinge Not Affected



Location of Hinge Canopy

Product Description:

Graco's Passage™, Alano™ and Spree™ Strollers and Travel Systems

Graco manufactured two different styles of hinge mechanisms for these stroller models. Only strollers or travel systems with a plastic, jointed hinge mechanism that has indented canopy positioning notches (see photo below) are included in this recall. The recalled strollers were manufactured between October 2004 and February 2008. The model number and manufacture date are located on the lower inside portion of the rear frame, just above the rear wheels.

Manufacturer:

Graco Children's Products Inc., of Atlanta, Ga.
Manufactured in China

Date Recall Posted:

1/20/10

UPC's carried in the Meijer Stores:

UPC	Description	Key
00000000-47406-06237-9	GRACO PASSAGE STROLLER LAURIN	214
00000000-47406-06241-6	GRACO 540 PASSAGE TRAVEL SYSTEM BANCROFT	214

UPC's carried on Meijer.com (ONLY affects items manufactured before March 2008) :

0-47406-08288-9 Graco Alano Travel System - Fortune
0-47406-08272-8 Graco Passage Travel System - Clara



Summary Of Recall:

The hinges on the stroller's canopy pose a fingertip amputation and laceration hazard to the child when the consumer is opening or closing the canopy.

What You Should Do:

Consumers should immediately stop using the recalled strollers and contact Graco to receive a free protective cover repair kit, or return product to your local Meijer store.

Consumer Contact Information:

For additional information, contact Graco at (800) 345-4109 between 8 a.m. and 5 p.m. ET Monday through Friday, or visit the firm's Web site at www.gracobaby.com