



Product Description: Evenflo Embrace™ Infant Car Seat/Carriers

The recall involves Evenflo Embrace™ Infant Car Seat/Carriers made before April 8, 2006. The recalled car seat/carriers have model numbers beginning with 317, 320, 397, 398, 540, 548, 549, 550, 556, 597, 598 or 599. The model number and production date information can be found on a white label on the bottom of the carrier and on the top of the convenience base. Models beginning with "5" are units sold with the travel system (compatible stroller). "Evenflo" is on the carrying handle and car seat base. Embrace™ infant car seat/carriers made on or after April 8, 2006 are not included in this recall.

Manufacturer: Evenflo Company Inc., of Vandalia, Ohio. Manufactured in the United States and China

Date Recall Posted: 5/11/07

UPCs: 0-32884-13828-9

Summary Of Recall: When used as an infant carrier, the handle can unexpectedly release, causing the seat to rotate forward. When this happens, an infant inside the carrier can fall to the ground and suffer serious injuries.

What You Should Do: Consumers should not use the handle until the repair kit has been installed. The product can continue to be used as a car seat when secured in a vehicle. Contact Evenflo to receive a free repair kit that strengthens the handle latch. Recall notice will be sent to all registered owners of the recalled product. The recalled units should not be returned to the retailer.

For additional information, contact Evenflo at (800) 490-7497 between 8 a.m. and 5 p.m. ET Monday through Friday or visit the recall Web site at www.embracehandle.com